

PERFORMANCE REQUIREMENTS SUMMARY
Avon Park Range, FL

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIREMENTS SUMMARY				
REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
RS01 General: Provide key personnel list & maintain a training program. Provide physical security and conserve utilities. (Ref para 1.2.4, 1.7 and Avon Park Range Annex para 1.2.6.1)	Maintain current personnel list and establish/implement training, security and conservation programs that protect personnel and equipment.	0% Lot: number of times reports are required.	100 percent inspection semi-annual checklist	1%
RS02 Quality assurance program. Establish and maintain a quality assurance plan, conduct and maintain inspections of all aspects of contractor performance requirements in PWS. (Ref para 1.4)	Maintain current quality assurance plan inspection checklists and inspection records that provide a comprehensive evaluation of the contractors performance established in the PWS.	0% Lot number of inspections conducted.	100 percent inspection quarterly checklist	2%
RS03 Administration: Prepare and maintain correspondence, logs, reports, and misc paperwork. Maintain information & safety bulletin boards, files, technical orders, publications and AFOSH library. Prepare maintenance/clearance schedule. (Ref PWS C-5, Ch 2, para 5.4)	Reports, correspondence/ miscellaneous paperwork should be prepared IAW applicable regulations. Logs/files shall provide complete history/audit trail.	0% Lot: number of times reports, logs and files are required.	100 percent inspection weekly/semi-annual checklist	1%

PERFORMANCE REQUIREMENTS SUMMARY
Avon Park Range, FL

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIREMENTS SUMMARY				
REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
RS04 Operation: Receive and maintain weekly range schedule, man scoring towers, RS04 Operation: Receive and maintain weekly range schedule, man scoring towers, spot score/record bomb impacts. Record flight line-up, prepare strafe pits and target areas, test acoustiscoring equipment. Perform range control officer duties. Be observant of fires, intruders, and ordnance releases out of range boundaries. Maintain training aides. (Ref PWS C-5, Ch. 2, para 5.1)	RS04 Operation: Receive and maintain weekly range schedule, man scoring towers,	0% Lot: Number of operational days in a month.	100 percent inspection Weekly Checklist Customer complaint	35%
RS05 Range Target Maintenance & Construction: prepares and moves target vehicles. Maintain bombing target arrays and strafe targets. (Ref PWS, Ch.2, para 5.2.1 and Avon Park Range Annex para 5.2.1)	Repair and replace all target vehicles as required. Maintain bombings target arrays/strafe targets as required by contract references.	0% Lot: number of targets repaired in a maintenance cycle	100 percent inspection weekly/quarterly/semi-annual/annual checklist.	29%
RS06 Roads, Grounds and Firebreaks. Maintain improved/unimproved roads firebreaks and grounds. (Ref PWS	Maintain roads, grounds, and firebreaks IAW PWS requirements.	0% Lot: number of operational days in a month.	100 percent inspection quarterly/annual checklist	12%

PERFORMANCE REQUIREMENTS SUMMARY
Avon Park Range, FL

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIREMENTS SUMMARY				
REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
C-5, Ch. 2, para 5.2.3)				
RS07 Environmental: Move and dispose of all hazardous, non-toxic and target waste to the appropriate facility. (Ref PWS C-5, Ch 2, para 5.3)	Provide required documentation and safe handling of all hazardous and non-toxic waste from the range to an appropriate facility or DRMO as required.	0% Lot: number of times documentation is required.	100 percent inspection weekly/semi-annual	2%
RS08 Maintain government furnished real property and capital equipment. (Ref C-5, Ch. 2, para 5.2.3)	Provide safe and economic repair to government furnished real property and equipment.	0% Lot: number of times maintenance is required.	100 percent inspection annual checklist	2%
RS09 Perform Custodial housekeeping functions. (Ref C-5, Ch. 2, 5.2.5 and Avon Park Range E-2)	Range main buildings, towers, and main compound grounds must be cleaned and maintained as to ensure functionally and present a neat orderly appearance.	0% Lot: number of days in a month.	100 percent inspection weekly, quarterly, and semi-annual checklists.	2%
RS10 Support Airfield & Ground Operations (Ref Avon Park Annex Para 5.6 & 5.7)	Airfield and ground operations support shall be provided to preclude mission degradation, delays, or cancellation.	0% Lot: number of operational days in a month	100 percent inspection weekly checklist, customer complaint	14%

PERFORMANCE REQUIREMENTS SUMMARY
Dare County Electronic Combat Range, NC

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIREMENTS SUMMARY				
REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
Site Operations. C-5.1.	Compliance with procedures, requirements, and directives in the SOW.	Zero critical items and no more than 15% non-critical discrepancies on checklist A6-1. Lot size is the number of items on checklist.	Checklist	8%
Operate Communications equipment. C-5.1.1	Compliance with procedures, requirements, and directives in the SOW.	Zero critical item or no more than 15% non-critical discrepancies on checklist A6-2. Lot size is number of items on checklist.	Checklist	2%
Conduct test, perform validation, and implement changes to Govt provided software. C-5.1.2	Compliance with procedures, requirements, and directives in the SOW.	Zero deficiencies. Checklist A6-3.	Checklist	1%
Operate Electronic Combat Equipment (AN/MSQ-T43) C-5.1., 5.1.3, 5.1.6	Compliance with procedures, requirements, and directives in the SOW.	Zero Critical items and no more than 15% non-critical discrepancies on checklist A6-26. Lot size is number of items on checklist.	Checklist	5%
Operate Electronic Combat Equipment (AN/MPQ-T3). C-5.1., 5.1.3, 5.1.6	Compliance with procedures, requirements, and directives in the SOW.	Zero critical items and no more than 15% non-critical discrepancies on checklist A6-27. Lot size is number of items on checklist.	Checklist	5%
Operate Electronic Combat Equipment (AN/VPQ-1). C-5.1., 5.1.3, 5.1.6	Compliance with procedures, requirements, and directives in the SOW.	Zero critical items and no more than 15% non-critical discrepancies on checklist A6-28. Lot size is number of items on checklist.	Checklist	5%
Operate Electronic Combat Equipment (AN/TPX-54). C-5.1., 5.1.3, 5.1.6	Compliance with procedures, requirements and directives in the SOW.	Zero critical items and no more than 15% non-critical discrepancies on checklist A6-29. Lot size is number of items on checklist.	Checklist	3%

PERFORMANCE REQUIREMENTS SUMMARY
Dare County Electronic Combat Range, NC

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIREMENTS SUMMARY				
REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
Perform Maintenance Control Function C-5.2.1	Compliance with procedures, requirements, and directives in the SOW.	No more than one critical or three non-critical discrepancies on checklist A6-14. Lot size is the number of items on checklist.	Checklist	2%
Maintain assigned range equipment (AN/VPQ-1). C-5.2.2	Compliance with procedures, requirements and directives in SOW	Operational Availability Checklist A6-31.	MIS	12%
Maintain assigned range equipment (AN/MSQ-T43). C-5.2.2	Compliance with procedures, requirements and directives in SOW	Operational Availability Checklist A6-31.	MIS	19%
Maintain assigned range equipment (AN/MPQ-T3). C-5.2.2	Compliance with procedures, requirements and directives in SOW	Operational Availability Checklist A6-31.	MIS	19%
Maintain assigned range equipment (AN/TPX-54). C-5.2.2	Compliance with procedures, requirements and directives in SOW	Operational Availability. Checklist A6-31.	MIS	6%
Maintain TODO/PDO Libraries. C-6	Compliance with procedures, requirements, and directives in the SOW.	No more than one critical or three non-critical discrepancies on checklist A6-20. No more than 8 defects/mo. Lot size is the number of Technical Orders, Commercial Manuals, publications, and contractor developed items.	Checklist	2%

PERFORMANCE REQUIREMENTS SUMMARY
Dare County Electronic Combat Range, NC

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIREMENTS SUMMARY				
REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
Develop, implement, and maintain Quality Control inspection system. C-5.6	Compliance with procedures, requirements and directives in the SOW.	No more than one defect on checklist A6-21. Lot size is the number of items on checklist.	Checklist	4%
Manage logistics support and maintain account, and preserve government furnished equipment. C-5.2.11, 5.5	Compliance with procedures, requirements, and directives in the SOW.	No more than one critical or six non-critical discrepancies on checklist A6-22. Lot size is the number of items on checklist.	Checklist	3%
Maintenance and Repair of Facilities, Roads, and Grounds. C-5.2.10	Compliance with procedures, requirements, and directives in the SOW/contract	No more than three deficient items on checklist A6-24. Lot size is the number of items on checklist.	Checklist	2%
Develop, implement, and maintain an Environmental Management Program. C-5.3	Compliance with procedures, requirements, and directives in the SOW/contract.	No more than five minor deficiencies on checklist A6-25.	Checklist	2%

PERFORMANCE REQUIREMENTS SUMMARY
Dare County Range, NC (B&G)

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIREMENT STANDARDS				
REQUIRED SERVICES	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
RS01 General: Provide key personnel list & maintain a training program. Provide physical security and conserve utilities. (Ref para 1.2.4, 1.7 and Dare County B&G Range Annex para 1.5)	Maintain current personnel list and establish/implement training, security and conservation programs that protect personnel and equipment.	0% lot: number of times reports are required.	100 percent inspection semi-annual checklist	1%
RS02 Quality assurance program. Establish and maintain a quality assurance plan, conduct and maintain inspections of all aspects of contractor performance requirements in PWS. (Ref para 1.4)	Maintain current quality assurance plan inspection checklists and inspection records that provide a comprehensive evaluation of the contractors performance established in the PWS.	0% Lot number of inspections conducted.	100 percent inspection quarterly checklist	2%
RS03 Administration: Prepare and maintain correspondence, logs, reports, and misc paperwork. Maintain information & safety bulletin boards, files, technical orders, publications and AFOSH library. Prepare information & safety bulletin boards, files, technical orders, publications and AFOSH library. Prepare maintenance/clearance schedule. Provide courier	Reports, correspondence/miscellaneous paperwork should be prepared IAW applicable regulations. Logs/files shall provide complete history/audit trail.	0% Lot: number of times reports, logs and files are required.	100 percent inspection weekly/semi-annual checklist	1%

PERFORMANCE REQUIREMENTS SUMMARY
Dare County Range, NC (B&G)

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIREMENTS SUMMARY				
REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
service. (Ref PWS C-5, Ch. 2, para 5.4)				
RS04 Operation: Receive and maintain weekly range schedule man scoring towers, spot score/record bomb impacts. Record flight line-up, prepare strafe pits and target areas, test acoustiscoring equipment. Perform range control officer duties. Be observant of fires, intruders, and ordnance releases out of range boundaries. Maintain training aides. (Ref PWS, C-5, Ch.2, para 5.1)	Range systems shall be capable of operation to preclude mission delays or cancellation. Score bombs, complete reports, inspect strafe pits, poles, berms, and target panels.	0% Lot: Number of operational days in a month.	100 percent inspection Weekly Checklist Customer complaint	37%
RS05 Range Target Maintenance & Construction: prepares and moves target vehicles. Maintain bombing target arrays and strafe targets. (Ref PWS, Ch.2, para 5.2.1 and Dare County B&G Range Annex para 5.2.1)	Repair and replace all target vehicles as required. Maintain bombings target arrays/strafe targets as required by contract references.	0% Lot: number of targets repaired in a maintenance cycle	100 percent inspection weekly/quarterly/semi-annual/annual checklist.	29%
PERFORMANCE REQUIREMENTS SUMMARY				

PERFORMANCE REQUIREMENTS SUMMARY
Dare County Range, NC (B&G)

Solicitation No.
F-44650-99-R0002

REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
RS06 Clearances: Perform required clearances. (Ref PWS, C-5, Ch.2, para 5.2.2)	Clearance will be completed safely during prescribed times outlined in AFI 13-212.	0% Lot: number of target areas cleared during a clearance cycle.	100 percent inspection quarterly/semi-annual/annual	5%
RS07 Roads, Grounds and Firebreaks. Maintain improved,/unimproved roads firebreaks and grounds. (Ref PWS C-5,	Maintain roads, grounds, and firebreaks IAW PWS requirements.	0% Lot: number of operational days in a month.	100 percent inspection quarterly/annual checklist	2%
RS08 Environmental: Move and dispose of all hazardous, non-toxic and target waste to the appropriate facility. (Ref PWS C-5, Ch 2, para 5.3 and Dare County B&G Range Annex para 5.3.1)	Provide required documentation and safe handling of all hazardous and non-toxic waste from the range to an appropriate facility or DRMO as required.	0% Lot: number of times documentation is required.	100 percent inspection weekly/semi-annual	2%
RS09 Maintain government furnished real property and capital equipment. (Ref PWS C-5, Ch 2, para 5.2.3)	Provide safe and economic repair to government furnished real property and equipment.	0% Lot: number of times maintenance is required.	100 percent inspection annual checklist	3%
RS10 Perform Custodial housekeeping functions. (Ref PWS C-5, Ch 2, para 5.2.5 and Dare County B&G Range TE-2)	Range main buildings, towers, and main compound grounds must be cleaned and maintained as to ensure functionally and present a neat and orderly appearance.	0% Lot: number of days in a month.	100 percent inspection weekly, quarterly, and semi-annual checklists.	3%
PERFORMANCE REQUIREMENTS SUMMARY				

PERFORMANCE REQUIREMENTS SUMMARY
Dare County Range, NC (B&G)

Solicitation No.
F-44650-99-R0002

REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENTS
RS11 Provide Fire Suppression and Crash Recovery as required. Develop and implement supporting training programs (Ref PWS C-5, Ch 2, para 5.7 and Dare County B&G Range Annex para 3.2.21.2)	Ensure a responsive, effective fire suppression and crash recovery program exists to minimize damage to government property/resources.	0% Lot: number of operational days in a month	100 percent inspection semi-annual checklist	3%
RS12 Provide Foliage Control Maintenance (Ref PWS C-5, Ch 2, para 5.2 and Dare County B&G Range TE-11)	Control Range Foliage and cut grass IAW PWS	0% Lot: number of times maintenance is required	100 percent 1st year and every 3rd year of contract thereafter	2%

PERFORMANCE REQUIREMENTS SUMMARY
ESS Ranges
Belle Fourche ND, La Junta CO, Harrison AR, Granite Peak UT

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIREMENTS SUMMARY				
REQUIRED SERVICES	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
Site Operations. C-5.1.	Compliance with procedures, requirements and directives in the SOW.	Zero critical items or no more than 15% non-critical discrepancies on checklist A6-1. Lot size is number of items on checklist.	Checklist	5%
Operate Communications equipment. C-5.1.1	Compliance with procedures, requirements and directives in the SOW.	Zero critical items or no more than 15% non-critical discrepancies on checklist A6-2. Lot size is number of items on checklist.	Checklist	2%
Conduct test, perform validation, and implement changes to Govt provided software C-5.1.2.	Compliance with requirements in the SOW.	Zero deficiencies on Checklist A6-3.	Checklist	1%
Operate Radar Bomb Scoring (RBS) Equipment (AN/TPQ-43). C-5.1, 5.1.3, 5.1.6	Compliance with procedures, requirements and directives in the SOW.	Zero critical items and no more than 15% non-critical discrepancies on checklist A6-4. Lot size is number of items on A6-4	Checklist	3%
Operate Electronic Combat Equipment (AN/MST-T1A). C-5.1, 5.1.3, 5.1.6	Compliance with procedures, requirements and directives in the SOW.	Zero critical items and no more than 15% non-critical discrepancies on checklist A6-5. Lot size is number of items on A6-5	Checklist	3%
Operate Electronic Combat Equipment (AN/MSR-T4). C-5.1, 5.1.3, 5.1.6	Compliance with procedures, requirements and directives in the SOW.	Zero critical item and no more than 15% non-critical discrepancies on checklist A6-6. Lot size is number of items on A6-6.	Checklist	3%

PERFORMANCE REQUIREMENTS SUMMARY
ESS Ranges
Belle Fourche ND, La Junta CO, Harrison AR, Granite Peak UT

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIREMENTS SUMMARY				
REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
Operate Electronic Combat Equipment (AN/MST-T1V). C-5.1, 5.1.3, 5.1.6	Compliance with procedures, requirements and directives in the SOW.	Zero critical item and no more that 15% non-critical discrepancies on checklist A6-7. Lot size is number of items on A6-7.	Checklist	3%
Operate Electronic Combat Equipment (AN/MLQ-T4). C-5.1, 5.1.3, 5.1.6	Compliance with procedures, requirements and directives in the SOW.	Zero critical items and no more that 15% non-critical discrepancies on checklist A6-8. Lot size is number of items on A6-8	Checklist	2%
Operate Route Integration Instrumentation System (RIIS) terminal and associated equipment. C-5.1.1.2	Compliance with procedures, requirements and directives in the SOW.	Zero critical items and no more that 15% non-critical discrepancies on checklist A6-9. Lot size is number of items on checklist.	Checklist	3%
Score RBS mission activity. C-5.1.6.1	Compliance with procedures, requirements and directives in the SOW.	Abort NTE 4.3% per quarter. Lot size is number of releases per quarter. Checklist A6-10.	MIS	3%
Score electronic combat mission activity. C-5.1.6.2	Compliance with procedures, requirements and directives in the SOW.	Abort rate NTE 2.6% per month. Lot size is number of sorties per month. Checklist A6-11	MIS	3%
Maintain assigned RIIS equipment. C-5.2	Compliance with procedures, requirements and directives in the SOW.	Ao rate not less than 95%. Checklist A6-12	MIS	1%

PERFORMANCE REQUIREMENTS SUMMARY
ESS Ranges
Belle Fourche ND, La Junta CO, Harrison AR, Granite Peak UT

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIREMENTS SUMMARY				
REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
Maintain RIIS equipment. C-5.2.	Compliance with procedures, requirements and directives in the SOW.	NTE one critical or 15% non-critical discrepancies on checklist A6-13. Lot size: # of checklist items x # eq. items	Checklist	2%
Perform Maintenance Control Function. C-5.2.1	Compliance with procedures, requirements and directives in the SOW.	NTE one critical or three non-critical discrepancies. Lot size is number of items on checklist A6-14.	Checklist	1%
Maintain assigned range equipment. (AN/MST-T1A) C-5.2	Compliance with procedures, requirements and directives in the SOW.	System and individual transmitter Ao rates not less than 95%. Checklist A6-15. Lot size is number of transmitters.	MIS	(*) See tech exhibit 1, atch 1. 15%
Maintain assigned range equipment (AN/MSR-T4). C-5.2	Compliance with procedures, requirements and directives in the SOW.	Ao rate not less than 95%. Checklist A6-16.	MIS	6%
Maintain assigned range equipment (AN/MST-T1(V)). C-5.2.	Compliance with procedures, requirements and directives in the SOW.	Ao rate for MCG and each pedestal not less than 95%. Checklist A6-17.	MIS	(*) See tech exhibit 1, atch 2. 11%
Maintain assigned range equipment (AN/MLQ-T4). C-5.2.	Compliance with procedures, requirements and directives in the SOW.	Ao rate not less than 95% Checklist A6-18.	MIS	5%

PERFORMANCE REQUIREMENTS SUMMARY
ESS Ranges
Belle Fourche ND, La Junta CO, Harrison AR, Granite Peak UT

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIREMENTS SUMMARY				
REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
Maintain assigned range equipment (AN/TPQ-43). C-5.2	Compliance with procedures, requirements and directives in the SOW.	Ao rate not less than 95%. Checklist A6-19	MIS	7%
Maintain TODO/PDO Libraries. C-6	Compliance with procedures, requirements and directives in the SOW.	NTE one critical or three non-critical discrepancies. Checklist A6-20. Lot size is number of publications.	Checklist	1%
Develop, implement, and maintain a quality control inspection system. C-5.6	Compliance with procedures, requirements and directives in the SOW.	NTE one defect on checklist A6-21. Lot size is number of items on checklist.	Checklist	5%
Manage logistics support, and maintain, account for and preserve GFE. C-5.2.11, 5.5	Compliance with procedures, requirements and directives in the SOW.	NTE one critical or six non-critical discrepancies on checklist A6-22. Lot size is number of items on checklist	Checklist	2%
Perform landscape maintenance. C-5.2.8	Compliance with procedures, requirements and directives in the SOW.	NTE three deficient items on checklist A6-23. Lot size is number of items on checklist.	Checklist	1%
PERFORMANCE REQUIREMENTS SUMMARY				

PERFORMANCE REQUIREMENTS SUMMARY
ESS Ranges
Belle Fourche ND, La Junta CO, Harrison AR, Granite Peak UT

Solicitation No.
F-44650-99-R0002

REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
Maintain and repair facilities, roads and grounds. C_5.2.10	Compliance with procedures, requirements and directives in the SOW.	NTE three deficient items on checklist A6-24. Lot size is number of item on checklist.	Checklist	1%
Develop, implement and maintain an Environmental Management Program. C-5.3	Compliance with procedures, requirements and directives in the SOW.	NTE five minor deficiencies on checklist A6-25. Lot size is number of items on checklist.	Checklist	1%

PERFORMANCE REQUIREMENTS SUMMARY
Grand Bay Range, GA

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIREMENTS SUMMARY				
REQUIRED SERVICES	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
RS01 General: Provide key personnel list & maintain a training program. Provide physical security and conserve utilities. (Ref para 1.2.4, 1.7 and Grand Bay Range Annex para 1.2)	Maintain current personnel list and establish/implement training, security and conservation programs that protect personnel and equipment.	0% lot: number of times reports are required.	100 percent inspection semi-annual checklist	1%
RS02 Quality assurance program. Establish and maintain a quality assurance plan, conduct and maintain inspections of all aspects of contractor performance requirements in PWS. (Ref para 1.4)	Maintain current quality assurance plan inspection checklists and inspection records that provide a comprehensive evaluation of the contractors performance established in the PWS.	0% Lot number of inspections conducted.	100 percent inspection quarterly checklist	6%
RS03 Administration: Prepare and maintain correspondence, logs, reports, and misc paperwork. Maintain information & safety bulletin boards, files, technical orders, publications and AFOSH library. Prepare maintenance/clearance schedule. Provide courier service. (Ref PWS C-5, Ch 2, para 5.4)	Reports, correspondence/miscellaneous paperwork should be prepared IAW applicable regulations. Logs/files shall provide complete history/audit trail.	0% Lot: number of times reports, logs and files are required.	100 percent inspection weekly/semi-annual checklist	1%
PERFORMANCE REQUIREMENTS SUMMARY				

PERFORMANCE REQUIREMENTS SUMMARY
Grand Bay Range, GA

Solicitation No.
F-44650-99-R0002

REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
RS04 Operation: Receive and maintain weekly range schedule man scoring towers, spot score/record bomb impacts. Record flight line-up, prepare strafe pits and target areas, test acoustiscoring equipment. Perform range control officer duties. Be observant flight line-up, prepare strafe pits and target areas, test acoustiscoring equipment. Perform range control officer duties. Be observant	Range systems shall be capable of operation to preclude mission delays or cancellation. Score bombs, complete reports, inspect strafe pits, poles, berms, and target panels.	0% Lot: Number of operational days in a month.	100 percent inspection Weekly Checklist Customer complaint	32%
RS05 Range Target Maintenance & Construction: prepares and moves target vehicles. Maintain bombing target arrays and strafe targets. (Ref PWS C-5, Ch 2, para 5.2.1 and Grand Bay Range Annex para 5.2.1)	Repair and replace all target vehicles as required. Maintain bombings target arrays/strafe targets as required by contract references.	0% Lot: number of targets repaired in a maintenance cycle	100 percent inspection weekly/quarterly/semi-annual/annual checklist.	27%
RS06 Clearances: Perform required clearances. (Ref PWS C-5, Ch 2, para 5.2.2)	Clearance will be completed safely during prescribed times outlined in AFI 13-212.	0% Lot: number of target areas cleared during a clearance cycle.	100 percent inspection quarterly/semi-annual/annual	10%

PERFORMANCE REQUIREMENTS SUMMARY

Grand Bay Range, GA

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIREMENTS SUMMARY				
REQUIRED SERVICES	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
RS07 Roads, Grounds and Firebreaks. Maintain improved/unimproved roads firebreaks and grounds. (Ref PWS C-5, Ch 2, para 5.2.3 and Grand Bay Range Annex para 5.2.3)	Maintain roads, grounds, and firebreaks IAW PWS requirements.	0% Lot: number of operational days in a month.	100 percent inspection quarterly/annual checklist	6%
RS08 Environmental: Move and dispose of all hazardous, non-toxic and target waste to the appropriate facility. (Ref PWS C-5, Ch 2 para 5.3 and Grand Bay Range Annex para 5.3.1)	Provide required documentation and safe handling of all hazardous and non-toxic waste from the range to an appropriate facility or DRMO as required.	0% Lot: number of times documentation is required.	100 percent inspection weekly/semi-annual	2%
RS09 Maintain government furnished real property and capital equipment. (Ref PWS C-5, Ch. 2, para 5.2.3)	Provide safe and economic repair to government furnished real property and equipment.	0% Lot: number of times maintenance is required.	100 percent inspection annual checklist	3%
RS10 Perform Custodial housekeeping functions. (Ref PWS C-5, Ch. 2, para 5.2.5 and Grand Bay Range TE-2)	Range main buildings, towers, and main compound grounds must be cleaned and maintained as to ensure functionally and present a neat orderly appearance.	0% Lot: number of days in a month.	100 percent inspection weekly, quarterly, and semi-annual checklists.	1%
RS11 Provide Fire Suppression and Crash Recovery as required. Develop and implement supporting training programs (Ref para PWS C-5, Ch 2, para 4.20 and para 5.7)	Ensure a responsive, effective fire suppression and crash recovery program exists to minimize damage to government property/resources.	0% Lot: number of operational days in a month	100 percent inspection semi-annual checklist	3%

PERFORMANCE REQUIREMENTS SUMMARY
Grand Bay Range, GA

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIREMENTS SUMMARY				
REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
RS12 Grass Cutting semi-improved (ref Grand Bay Range Annex para 5.2.3.2.7)	Grass shall not be cut less than 4" and no more than 6" high, contractor shall weed eat around ponds down to water line, and around target vehicles, etc.	0% Number of cuttings	100% Quarterly Inspection	3%
Location 1 Powers Rd area Location 2 Bemiss Field Location 3 Impact Area	Cut 12 times per year Cut 3 times per year Cut 3 times per year Zones 1,2,3, except Zone 1, cut 4 times per year			
RS13 Grass Cutting Improved grounds, main compound and visitor viewing area (Ref Grand Bay Range Annex para 5.2.3.1.8)	Cutting height shall not be less than one and one half inches and no more than 4", trim around all structures, walk ways, deck, blow/sweep clippings from walk ways, cut 16 times per year	0% Number of cuttings	100 % Weekly Inspection	1%
RS14 Foliage Control Option 1, Clear cut foliage, as shown on map TE-3, using track type vehicle	Trees and brush shall be cut no more than 1" above the water line, and as low as possible	0% Number of cuttings	100% 1st year and every 3rd year of contract thereafter	4%

PERFORMANCE REQUIREMENTS SUMMARY
Grand Bay Range, GA

Solicitation No.
F-44650-99-R0002

REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
RS14 Foliage Control Option 2, Contractor shall Herbicide area as shown in TE-3 map (Ref Grand Bay Range Annex 5.2.3.1.9)	Contractor shall herbicide the area noted in the map in lieu of mechanically cutting the trees and brush. Command and Base environmental shall determine type of herbicide and method of application. Note: Contracting Officer will pick Option 1 or 2	0% Number of operations	100% 1st year and every 3rd year of contract thereafter	same as above, only one will be chosen

PERFORMANCE REQUIREMENTS SUMMARY
Holloman Ranges, NM

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIREMENTS SUMMARY				
REUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
RS01 General: Provide key personnel list & maintain a training program. Provide physical security and conserve utilities. (Ref para 1.2.4, 1.7 and Holloman Range Annex para 1.2)	Maintain current personnel list and establish/implement training, security and conservation programs that protect personnel and equipment.	0% lot: number of times reports are required.	100 percent inspection semi-annual checklist	1%
RS02 Quality assurance program. Establish and maintain a quality assurance plan, conduct and maintain inspections of all aspects of contractor performance requirements in PWS. (Ref para 1.4)	Maintain current quality assurance plan inspection checklists and inspection records that provide a comprehensive evaluation of the contractors performance established in the PWS.	0% Lot number of inspections conducted.	100 percent inspection quarterly checklist	2%
RS03 Administration: Prepare and maintain correspondence, logs, reports, and misc paperwork. Maintain information & safety bulletin boards, files, technical orders, publications and AFOSH library. Prepare maintenance/clearance schedule. Provide courier service. (Ref PWS C-5, Ch. 2, para 5.4)	Reports, correspondence/miscellaneous paperwork should be prepared IAW applicable regulations. Logs/files shall provide complete history/audit trail.	0% Lot: number of times reports, logs and files are required.	100 percent inspection weekly/semi-annual checklist	1%
PERFORMANCE REQUIREMENTS SUMMARY				

PERFORMANCE REQUIREMENTS SUMMARY
Holloman Ranges, NM

Solicitation No.
F-44650-99-R0002

REQUIRED SERVICES	STANDARD	PERFORMANCE REQUIREMENTS	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
RS04 Operation: Receive and maintain weekly range schedule man scoring towers, spot score/record bomb impacts. Record flight line-up, prepare strafe pits and target areas, test acoustiscoring equipment. Perform range control officer duties. Be observant of fires, intruders, and ordnance releases out of range boundaries. Maintain training aides. (Ref PWS C-5, Ch. 2, para 5.1)	Range systems shall be capable of operation to preclude mission delays or cancellation. Score bombs, complete reports, inspect strafe pits, poles, berms, and target panels.	0% Lot: Number of operational days in a month.	100 percent inspection Weekly Checklist Customer complaint	38%
RS05 Range Target Maintenance & Construction: prepares and moves target vehicles. Maintain bombing target arrays and strafe targets. (Ref PWS, Ch. 2, para 5.2.1 and Holloman Range Annex para 5.2.1)	Repair and replace all target vehicles as required. Maintain bombings target arrays/strafe targets as required by contract references.	0% Lot: number of targets repaired in a maintenance cycle	100 percent inspection weekly/quarterly/semi-annual/annual checklist.	29%
RS06 Clearances: Perform required clearances. (Ref PWS C-5, Ch. 2, para 5.2.2)	Clearance will be completed safely during prescribed times outlined in AFI 13-212.	0% Lot: number of target areas cleared during a clearance cycle.	100 percent inspection quarterly/semi-annual/annual	10%
PERFORMANCE REQUIREMENTS SUMMARY				

PERFORMANCE REQUIREMENTS SUMMARY
Holloman Ranges, NM

Solicitation No.
F-44650-99-R0002

REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
RS07 Roads, Grounds and Firebreaks. Maintain improved/unimproved roads firebreaks and grounds. (Ref. PWS C-5, Ch. 2, PARA 5.2.3.)	Maintain roads, grounds, and firebreaks IAW PWS requirements.	0% Lot: number of operational days in a month.	100 percent inspection quarterly/annual checklist	8%
RS08 Environmental: Move and dispose of all hazardous, non-toxic and target waste to the appropriate facility. (Ref PWS C-5, Ch. 2, para 5.3 and Holloman Range Annex para 5.3.1)	Provide required documentation and safe handling of all hazardous and non-toxic waste from the range to an appropriate facility or DRMO as required.	0% Lot: number of times documentation is required.	100 percent inspection weekly/semi-annual	2%
RS09 Maintain government furnished real property and capital equipment. (Ref PWS, C-5, Ch. 2, para 5.2.3)	Provide safe and economic repair to government furnished real property and equipment.	0% Lot: number of times maintenance is required.	100 percent inspection annual checklist	3%
RS10 Perform Custodial housekeeping functions. (Ref PWS, C-5, Ch. 2, 5.2.5 and Holloman Range TE-2)	Range main buildings, towers, and main compound grounds must be cleaned and maintained as to ensure functionally and present a neat orderly appearance.	0% Lot: number of days in a month.	100 percent inspection weekly, quarterly, and semi-annual checklists.	3%
RS11 Provide Fire Suppression and Crash Recovery as required. Develop and implement supporting training programs (Ref para 5.7)	Ensure a responsive, effective fire suppression and crash recovery program exists to minimize damage to government property/resources.	0% Lot: number of operational days in a month	100 percent inspection semi-annual checklist	3%

PERFORMANCE REQUIREMENTS SUMMARY
Melrose Electronic Combat Range, NM

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIREMENTS SUMMARY				
REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
Site Operations. C-5.1.	Compliance with procedures, requirements and directives in the SOW.	Zero critical items or no more than 15% non-critical discrepancies on checklist A6-1. Lot size is number of items on checklist.	Checklist	5%
Operate Communications equipment. C-5.1.1.	Compliance with procedures, requirements and directives in the SOW.	Zero critical items or no more than 15% non-critical discrepancies on checklist A6-2. Lot size is number of items on checklist.	Checklist	2%
Conduct test, perform validation, and implement changes to Govt provided software C-5.1.2.	Compliance with procedures, requirements and directives in the SOW.	Zero deficiencies on Checklist A6-3.	Checklist	1%
Operate Radar Bomb Scoring (RBS) Equipment (AN/TPQ-43). C-5.1, 5.1.3, 5.1.6	Compliance with procedures, requirements and directives in the SOW.	Zero critical items and no more that 15% non-critical discrepancies on checklist A6-4. Lot size is number of items on A6-4	Checklist	5%
Operate Electronic Combat Equipment (AN/MST-T1A). C-5.1, 5.1.3, 5.1.6	Compliance with procedures, requirements and directives in the SOW.	Zero critical items and no more that 15% non-critical discrepancies on checklist A6-5. Lot size is number of items on A6-5	Checklist	5%
Operate Electronic Combat Equipment (AN/MSR-T4). C-5.1, 5.1.3, 5.1.6	Compliance with procedures, requirements and directives in the SOW.	Zero critical item and no more that 15% non-critical discrepancies on checklist A6-6. Lot size is number of items on A6-6.	Checklist	4%

PERFORMANCE REQUIREMENTS SUMMARY
Melrose Electronic Combat Range, NM

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIREMENTS SUMMARY				
REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
Operate Electronic Combat Equipment (AN/MST-T1V). C-5.1, 5.1.3, 5.1.6	Compliance with procedures, requirements and directives in the SOW.	Zero critical items and no more that 15% non-critical discrepancies on checklist A6-7. Lot size is number of items on A6-7	Checklist	4%
Operate Electronic Combat Equipment (AN/VPQ-1). C-5.1, 5.1.3, 5.1.6.	Compliance with procedures, requirements and directives in the SOW.	More that 15% non-critical discrepancies on checklist A6-28. Lot size is number of items on checklist.	Checklist	4%
Operate Route Integration Instrumentation System (RIIS) terminal and associated equipment. C-5.1.1.2.	Compliance with procedures, requirements and directives in the SOW.	Zero critical items and no more that 15% non-critical discrepancies on checklist A6-2. Lot size is number of items on checklist.	Checklist	4%
Score RBS mission activity. C-5.1.6.1	Compliance with procedures, requirements and directives in the SOW.	Abort NTE 4.3% per quarter. Lot size is number of sorties per quarter. Checklist A6-10.	MIS	5%
Score electronic combat mission activity. C-5.1.6.2.	Compliance with procedures, requirements and directives in the SOW.	Abort rate NTE 2.6% per month. Lot size is number of sorties per month. Checklist A6-11.	MIS	1%

PERFORMANCE REQUIREMENTS SUMMARY
Melrose Electronic Combat Range, NM

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIEMENTS SUMMARY				
REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENTS	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
Maintain assigned RIIS equipment. C-5.2	Compliance with procedures, requirements and directives in the SOW.	Ao rate not less than 95%. Checklist A6-12	MIS	2%
Maintain RIIS equipment. C-5.2.	Compliance with procedures, requirements and directives in the SOW.	NTE one critical or 15% non-critical discrepancies on checklist A6-13. Lot size: # of checklist items x # eq. items	Checklist	2%
Perform Maintenance Control Function. C-5.2.1.	Compliance with procedures, requirements and directives in the SOW.	NTE one critical or three non-critical discrepancies. Lot size is number of items on checklist A6-14.	Checklist	1%
Maintain assigned range equipment. (AN/MST-T1A) C-5.2	Compliance with procedures, requirements and directives in the SOW.	System and individual transmitter Ao rates not less that 95%. Checklist A6-15. Lot size is number of transmitters.	MIS	(*) See tech exhibit 1, atch 1. 13%
Maintain assigned range equipment (AN/MSR-T4). C-5.2	Compliance with procedures, requirements and directives in the SOW.	Ao rate not less than 95%. Checklist A6-16.	MIS	6%

PERFORMANCE REQUIREMENTS SUMMARY
Melrose Electronic Combat Range, NM

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIREMENTS SUMMARY				
REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
Maintain assigned range equipment (AN/MST-T1(V)). C-5.2.	Compliance with procedures, requirements and directives in the SOW.	Ao rate for MCG and each pedestal not less than 95%. Checklist A6-17.	MIS	(*) See tech exhibit 1, atch 2. 13%
Maintain assigned range equipment (AN/VPQ-1). C-5.2.	Compliance with procedures, requirements and directives in the SOW.	Ao rate not less than 95% Checklist A6-31.	MIS	4%
Maintain assigned range equipment (AN/TPQ-43). C-5.2	Compliance with procedures, requirements and directives in the SOW.	Ao rate not less than 95%. Checklist A6-19	MIS	8%
Maintain TODO/PDO Libraries. C-6	Compliance with procedures, requirements and directives in the SOW.	NTE one critical or three non-critical discrepancies. Checklist A6-20. Lot size is number of publications.	Checklist	1%
Develop, implement, and maintain a quality control inspection system. C-5.6	Compliance with procedures, requirements and directives in the SOW.	NTE one defect on checklist A6-21. Lot size is number of items on checklist.	Checklist	3%

PERFORMANCE REQUIREMENTS SUMMARY
Melrose Electronic Combat Range, NM

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIREMENTS SUMMARY				
REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
Manage logistics support, and maintain, account for and preserve GFE. C-5.2.11	Compliance with procedures, requirements and directives in the SOW.	NTE one critical or six non-critical discrepancies on checklist A6-22. Lot size is number of items on checklist	Checklist	2%
Perform landscape maintenance. C-5.2.8	Compliance with procedures, requirements and directives in the SOW.	NTE three deficient items on checklist A6-23. Lot size is number of items on checklist.	Checklist	1%
Maintain and repair facilities, roads and grounds. C-5.2.10	Compliance with procedures, requirements and directives in the SOW.	NTE three deficient items on checklist A6-24. Lot size is number of item on checklist.	Checklist	1%
Develop, implement and maintain an Environmental Management Program. C-5.3	Compliance with procedures, requirements and directives in the SOW.	NTE five minor deficiencies on checklist A6-25. Lot size is number of items on checklist.	Checklist	1%

PERFORMANCE REQUIREMENTS SUMMARY
Melrose Range, NM (B&G)

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIREMENTS SUMMARY				
REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENTS
RS01 General: Provide key personnel list & maintain a training program. Provide physical security and conserve utilities. (Ref para 1.2, 1.7, and Melrose B&G Range Annex para 1.2)	Maintain current personnel list and establish/implement training, security and conservation programs that protect personnel and equipment.	0% lot: number of times reports are required.	100 percent inspection semi-annual checklist	1%
RS02 Quality assurance program. Establish and maintain a quality assurance plan, conduct and maintain inspections of all aspects of contractor performance requirements in PWS. (Ref para 1.4)	Maintain current quality assurance plan inspection checklists and inspection records that provide a comprehensive evaluation of the contractors performance established in the PWS.	0% Lot: number of inspections conducted.	100 percent inspection quarterly checklist	2%
RS03 Administration: Prepare and maintain correspondence, logs, reports, and misc paperwork. Maintain information & safety bulletin boards, files, technical orders, publications and AFOSH library. Prepare maintenance/clearance schedule. Provide courier service. (Ref PWS C-5, Ch 2, para 5.4)	Reports, correspondence/ miscellaneous paperwork should be prepared IAW applicable regulations. Logs/files shall provide complete history/audit trail.	0% Lot: number of times reports, logs and files are required.	100 percent inspection weekly/semi-annual checklist	1%

PERFORMANCE REQUIREMENTS SUMMARY
Melrose Range, NM (B&G)

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIREMENTS SUMMARY				
REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
RS04 Operation: Receive and maintain weekly range schedule man scoring towers, spot score/record bomb impacts. Record flight line-up, prepare strafe pits and target areas, test acoustiscoring equipment. Perform range control officer duties. Be observant of fires, intruders, and ordnance releases out of range boundaries. Maintain training aides. (Ref PWS C-5, Ch 2 para 5.1 and Melrose B&G Range Annex para 5.1)	Range systems shall be capable of operation to preclude mission delays or cancellation. Score bombs, complete reports, inspect strafe pits, poles, berms, and target panels.	0% Lot: Number of operational days in a month.	100 percent inspection Weekly Checklist Customer complaint	38%
RS05 Range Target Maintenance & Construction: prepares and moves target vehicles. Maintain bombing target arrays and strafe targets. (Ref PWS C-5, Ch 2, para 5.2.1 and Melrose B&G Range Annex para 5.2.1)	Repair and replace all target vehicles as required. Maintain bombings target arrays/strafe targets as required by contract references.	0% Lot: number of targets repaired in a maintenance cycle	100 percent inspection weekly/quarterly/semi-annual/annual checklist.	29%
RS06 Clearances: Perform required clearances. (Ref PWS C-5, Ch 2, para 5.2.2)	Clearance will be completed safely during prescribed times outlined in AFI 13-212.	0% Lot: number of target areas cleared during a clearance cycle.	100 percent inspection quarterly/semi-annual/annual	10%

PERFORMANCE REQUIREMENTS SUMMARY
Melrose Range, NM (B&G)

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIREMENTS SUMMARY				
REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
RS07 Roads, Grounds and Firebreaks. Maintain improved/unimproved roads firebreaks and grounds. (Ref PWS C-5, Ch 2, para 5.2.3)	Maintain roads, grounds, and firebreaks IAW PWS requirements.	0% Lot: number of operational days in a month.	100 percent inspection quarterly/annual checklist	11%
RS08 Environmental: Move and dispose of all hazardous, non-toxic and target waste to the appropriate facility. (Ref PWS C-5, Ch 2 para 5.3.1 and Melrose B&G Range Annex para 5.3)	Provide required documentation and safe handling of all hazardous and non-toxic waste from the range to an appropriate facility or DRMO as required.	0% Lot: number of times documentation is required.	100 percent inspection weekly/semi-annual	2%
RS09 Maintain government furnished real property and capital equipment. (Ref PWS C-5, Ch 2, para 5.2.3)	Provide safe and economic repair to government furnished real property and equipment.	0% Lot: number of times maintenance is required.	100 percent inspection annual checklist	3%
RS10 Perform Custodial housekeeping functions. (Ref PWS C-5, Ch 2, para 5.2.5 and Melrose B&G Range TE-2)	Range main buildings, towers, and main compound grounds must be cleaned and maintained as to ensure functionally and present a neat orderly appearance.	0% Lot: number of days in a month.	100 percent inspection weekly, quarterly, and semi-annual checklists.	3%

PERFORMANCE REQUIREMENTS SUMMARY
Poinsett Electronic Combat Range, SC

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIREMENTS SUMMARY				
REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVWEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
Site Operations. C-5.1.	Compliance with procedures, requirements and directives in the SOW.	Zero critical items or no more than 15% non-critical discrepancies on checklist A6-1. Lot size is number of items on checklist.	Checklist	12%
Operate Communications equipment. C-5.1.1.	Compliance with procedures, requirements and directives in the SOW.	Zero critical items or no more than 15% non-critical discrepancies on checklist A6-2. Lot size is number of items on checklist.	Checklist	4%
Conduct test, perform validation, and implement changes to Govt provided software C-5.1.2.	Compliance with procedures, requirements and directives in the SOW.	Zero deficiencies on Checklist A6-3.	Checklist	1%
Operate Radar Bomb Scoring (RBS) Equipment (AN/TPQ-43). C-5.1, 5.1.3, 5.1.6	Compliance with procedures, requirements and directives in the SOW.	Zero critical items and no more that 15% non-critical discrepancies on checklist A6-4. Lot size is number of items on A6-4	Checklist	1%
Operate Electronic Combat Equipment (AN/MST-T1A). C-5.1, 5.1.3, 5.1.6	Compliance with procedures, requirements and directives in the SOW.	Zero critical items and no more that 15% non-critical discrepancies on checklist A6-5. Lot size is number of items on A6-5	Checklist	6%
PERFORMANCE REQUIREMENTS SUMMARY				

PERFORMANCE REQUIREMENTS SUMMARY

Poinsett Electronic Combat Range, SC

Solicitation No.
F-44650-99-R0002

REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
Operate Electronic Combat Equipment (AN/MSR-T4). C-5.1, 5.1.3, 5.1.6	Compliance with procedures, requirements and directives in the SOW.	Zero critical item and no more that 15% non-critical discrepancies on checklist A6-6. Lot size is number of items on A6-6.	Checklist	2%
Operate Electronic Combat Equipment (AN/MST-T1V). C-5.1, 5.1.3, 5.1.6	Compliance with procedures, requirements and directives in the SOW.	Zero critical items and no more that 15% non-critical discrepancies on checklist A6-7. Lot size is number of items on A6-7	Checklist	6%
Operate Electronic Combat Equipment (AN/VPQ-1). C-5.1, 5.1.3, 5.1.6	Compliance with procedures, requirements and directives in the SOW.	Zero critical items and no more that 15% non-critical discrepancies on checklist A6-28. Lot size is number of items on checklist.	Checklist	3%
Operate Electronic Combat Equipment (AN/SPS-66) C-5.1, 5.1.3, 5.1.6	Compliance with procedures, requirements and directives in the SOW.	Zero critical items and no more that 15% non-critical discrepancies on checklist A6-30. Lot size is number of items on checklist. 1%	Checklist	1%
Score RBS mission activity. C-5.1.6.1	Compliance with procedures, requirements and directives in the SOW.	Abort NTE 4.3% per quarter. Lot size is number of sorties per quarter. Checklist A6-10.	MIS	2%
Score electronic combat mission activity. C-5.1.6.2	Compliance with procedures, requirements and directives in the SOW.	Abort rate NTE 2.6% per month. Lot size is number of sorties per month. Checklist A6-11	MIS	1%
PERFORMANCE REQUIREMENTS SUMMARY				

PERFORMANCE REQUIREMENTS SUMMARY

Poinsett Electronic Combat Range, SC

Solicitation No.
F-44650-99-R0002

REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
Maintain assigned equipment (AN/SPS-66) C-5.2	Compliance with procedures, requirements and directives in the SOW.	Ao rate not less than 95%. Checklist A6-31	MIS	1%
Maintain RIIS equipment. C-5.2.	Compliance with procedures, requirements and directives in the SOW.	NTE one critical or 15% non-critical discrepancies on checklist A6-13. Lot size: # of checklist items x # eq. items	Checklist	N/A
Perform Maintenance Control Function. C-5.2.1	Compliance with procedures, requirements and directives in the SOW.	NTE one critical or three non-critical discrepancies. Lot size is number of items on checklist A6-14.	Checklist	1%
Maintain assigned range equipment. (AN/MST-T1A) C-5.2	Compliance with procedures, requirements and directives in the SOW.	System and individual transmitter Ao rates not less than 95%. Checklist A6-15. Lot size is number of transmitters.	MIS	(*) See tech exhibit 1, atch 1. 14%
Maintain assigned range equipment (AN/MSR-T4). C-5.2	Compliance with procedures, requirements and directives in the SOW.	Ao rate not less than 95%. Checklist A6-16.	MIS	4%
Maintain assigned range equipment (AN/MST-T1(V)). C-5.2.	Compliance with procedures, requirements and directives in the SOW.	Ao rate for MCG and each pedestal not less than 95%. Checklist A6-17	MIS	(*) See tech exhibit 1, atch 2. 15%
Maintain assigned range equipment (AN/VPQ-1). C-5.2	Compliance with procedures, requirements and directives in the SOW.	Ao rate not less than 95% Checklist A6-31	MIS	10%
PERFORMANCE REQUIREMENTS SUMMARY				

PERFORMANCE REQUIREMENTS SUMMARY

Poinsett Electronic Combat Range, SC

Solicitation No.
F-44650-99-R0002

REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
Maintain assigned range equipment (AN/TPQ-43). C-5.2	Compliance with procedures, requirements and directives in the SOW.	Ao rate not less than 95%. Checklist A6-19.	MIS	2%
Maintain TODO/PDO Libraries. C-6	Compliance with procedures, requirements and directives in the SOW.	NTE one critical or three non-critical discrepancies. Checklist A6-20. Lot size is number of publications.	Checklist	1%
Develop, implement, and maintain a quality control inspection system. C-5.6	Compliance with procedures, requirements and directives in the SOW.	NTE one defect on checklist A6-21. Lot size is number of items on checklist.	Checklist	5%
Manage logistics support, and maintain, account for and preserve GFE. C-5.2.11	Compliance with procedures, requirements and directives in the SOW.	NTE one critical or six non-critical discrepancies on checklist A6-22. Lot size is number of items on checklist	Checklist	2%
Perform landscape maintenance. C-5.3.8	Compliance with procedures, requirements and directives in the SOW.	NTE three deficient items on checklist A6-23. Lot size is number of items on checklist.	Checklist	1%
Maintain and repair facilities, roads and grounds. C_5.2.10	Compliance with procedures, requirements and directives in the SOW.	NTE three deficient items on checklist A6-24. Lot size is number of item on checklist.	Checklist	1%
Develop, implement and maintain an Environmental Management Program. C-5.3	Compliance with procedures, requirements and directives in the SOW.	NTE five minor deficiencies on checklist A6-25. Lot size is number of items on checklist.	Checklist	1%

PERFORMANCE REQUIREMENTS SUMMARY
Poinsett Range, SC (B&G)

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIREMENTS SUMMARY				
REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
RS01 General: Provide key personnel list & maintain a training program. Provide physical security and conserve utilities. (Ref para 1.2, 1.7 and Poinsett B&G Range Annex para 1.2)	Maintain current personnel list and establish/implement training, security and conservation programs that protect personnel and equipment.	0% lot: number of times reports are required.	100 percent inspection semi-annual checklist	1%
RS02 Quality assurance program. Establish and maintain a quality assurance plan, conduct and maintain inspections of all aspects of contractor performance requirements in PWS. (Ref para 1.4)	Maintain current quality assurance plan inspection checklists and inspection records that provide a comprehensive evaluation of the contractors performance established in the PWS.	0% Lot: number of inspections conducted.	100 percent inspection quarterly checklist	2%
RS03 Administration: Prepare and maintain correspondence, logs, reports, and misc paperwork. Maintain information & safety bulletin boards, files, technical orders, publications and AFOSH library. Prepare maintenance/clearance schedule. Provide courier service. (Ref PWS C-5, Ch 2, para 5.4)	Reports, correspondence/miscellaneous paperwork should be prepared IAW applicable regulations. Logs/files shall provide complete history/audit trail	0% Lot: number of times reports, logs and files are required.	100 percent inspection weekly/semi-annual checklist	1%
PERFORMANCE REQUIREMENTS SUMMARY				

PERFORMANCE REQUIREMENTS SUMMARY
Poinsett Range, SC (B&G)

Solicitation No.
F-44650-99-R0002

REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
RS04 Operation: Receive and maintain weekly range schedule man scoring towers, spot score/record bomb impacts. Record flight line-up, prepare strafe pits and target areas, test acoustiscoring equipment. Perform range control officer duties. Be observant of fires, intruders, and ordnance releases out of range boundaries. Maintain training aides. (Ref PWS C-5, Ch 2, para 5.1)	Range systems shall be capable of operation to preclude mission delays or cancellation. Score bombs, complete reports, inspect strafe pits, poles, berms, and target panels.	0% Lot: Number of operational days in a month.	100 percent inspection Weekly Checklist Customer complaint	38%
RS05 Range Target Maintenance & Construction: prepares and moves target vehicles. Maintain bombing target arrays and strafe targets. (Ref PWS, C-5, Ch 2, para 5.2.1 and Poinsett B&G Range Annex para 5.2.1)	Repair and replace all target vehicles as required. Maintain bombings target arrays/strafe targets as required by contract references.	0% Lot: number of targets repaired in a maintenance cycle	100 percent inspection weekly/quarterly/semi-annual/annual checklist.	29%
RS06 Clearances: Perform required clearances. (Ref PWS C-5, Ch 2, para 5.2.2)	Clearance will be completed safely during prescribed times outlined in AFI 13-212.	0% Lot: number of target areas cleared during a clearance cycle.	100 percent inspection quarterly/semi-annual/annual	10%
PERFORMANCE REQUIREMENTS SUMMARY				

PERFORMANCE REQUIREMENTS SUMMARY
Poinsett Range, SC (B&G)

Solicitation No.
F-44650-99-R0002

REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
RS07 Roads, Grounds and Firebreaks. Maintain improved/unimproved roads firebreaks and grounds. (Ref PWS C-5, Ch 2, para 5.2.3 and Poinsett B&G Range TE-11)	Maintain roads, grounds, and firebreaks IAW PWS requirements.	0% Lot: number of operational days in a month.	100 percent inspection quarterly/annual checklist	11%
RS08 Environmental: Move and dispose of all hazardous, non-toxic and target waste to the appropriate facility. (Ref PWS C-5, Ch 2, para 5.3)	Provide required documentation and safe handling of all hazardous and non-toxic waste from the range to an appropriate facility or DRMO as required.	0% Lot: number of times documentation is required.	100 percent inspection weekly/semi-annual	2%
RS09 Maintain government furnished real property and capital equipment. (Ref PWS C-5, Ch 2, para 5.2.3)	Provide safe and economic repair to government furnished real property and equipment.	0% Lot: number of times maintenance is required.	100 percent inspection annual checklist	3%
RS10 Perform Custodial housekeeping functions. (Ref PWS C-5, Ch 2, para 5.2.5 and Poinsett B&G Range TE-2)	Range main buildings, towers, and main compound grounds must be cleaned and maintained as to ensure functionally and present a neat orderly appearance.	0% Lot: number of days in a month.	100 percent inspection weekly, quarterly, and semi-annual checklists.	3%

PERFORMANCE REQUIREMENTS SUMMARY
Saylor Creek/Juniper Butte Ranges, ID (B&G)

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIREMENTS SUMMARY				
REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
RS01 General: Provide key personnel list & maintain a training program. Provide physical security and conserve utilities. (Ref para 1.2.4, 1.7 and Saylor Creek Range Annex para 1.2)	Maintain current personnel list and establish/implement training, security and conservation programs that protect personnel and equipment.	0% Lot: number of times reports are required.	100 percent inspection semi-annual checklist	1%
RS02 Quality assurance program. Establish and maintain a quality assurance plan, conduct and maintain inspections of all aspects of contractor performance requirements in PWS. (Ref para 1.4)	Maintain current quality assurance plan inspection checklists and inspection records that provide a comprehensive evaluation of the contractors performance established in the PWS.	0% Lot: number of inspections conducted.	100 percent inspection quarterly checklist	2%
RS03 Administration: Prepare and maintain correspondence, logs, reports, and misc paperwork. Maintain information & safety bulletin boards, files, technical orders, publications and AFOSH library. Prepare maintenance/clearance schedule. Provide courier service. (Ref PWS C-5, Ch. 2, para 5.4)	Reports, correspondence/miscellaneous paperwork should be prepared IAW applicable regulations. Logs/files shall provide complete history/audit trail.	0% Lot: number of times reports, logs and files are required.	100 percent inspection weekly/semi-annual checklist	1%

PERFORMANCE REQUIREMENTS SUMMARY
Saylor Creek/Juniper Butte Ranges, ID (B&G)

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIREMENTS SUMMARY				
REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
RS04 Operation: Receive and maintain weekly range schedule man scoring towers, spot score/record bomb impacts. Record flight line-up, prepare strafe pits and target areas, test acoustiscoring equipment. Perform range control officer duties. Be observant of fires, intruders, and ordnance releases out of range boundaries. Maintain training aides. (Ref PWS C-5, Ch 2, para 5.1)	Range systems shall be capable of operation to preclude mission delays or cancellation. Score bombs, complete reports, inspect strafe pits, poles, berms, and target panels.	0% Lot: Number of operational days in a month.	100 percent inspection Weekly Checklist Customer complaint	34%
RS05 Range Target Maintenance & Construction: prepares and moves target vehicles. Maintain bombing target arrays and strafe targets. (Ref PWS, Ch.2, para 5.2.1 and Saylor Creek Range Annex para 5.2.1)	Repair and replace all target vehicles as required. Maintain bombings target arrays/strafe targets as required by contract references.	0% Lot: number of targets repaired in a maintenance cycle	100 percent inspection weekly/quarterly/semi-annual/annual checklist.	29%
RS06 Clearances: Perform required clearances. (Ref PWS, Ch.2, para 5.2.2)	Clearance will be completed safely during prescribed times outlined in AFI 13-212.	0% Lot: number of target areas cleared during a clearance cycle.	100 percent inspection quarterly/semi-annual/annual	10%

PERFORMANCE REQUIREMENTS SUMMARY
Saylor Creek/Juniper Butte Ranges, ID (B&G)

Solicitation No.
F-44650-99-R0002

PERFORMANCE REQUIREMENTS SUMMARY				
REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
RS07 Roads, Grounds and Firebreaks. Maintain improved,/unimproved roads firebreaks and grounds. (Ref PWS, Ch.2, para 5.2.3 and Saylor Creek Range Annex para 5.2.3)	Maintain roads, grounds, and firebreaks IAW PWS requirements.	0% Lot: number of operational days in a month.	100 percent inspection quarterly/annual checklist	12%
RS08 Environmental: Move and dispose of all hazardous, non-toxic and target waste to the appropriate facility. (Ref PWS C-5, Ch 2, para 5.3 and Saylor Creek Range Annex para 5.3.1)	Provide required documentation and safe handling of all hazardous and non-toxic waste from the range to an appropriate facility or DRMO as required.	0% Lot: number of times documentation is required.	100 percent inspection weekly/semi-annual	2%
RS09 Maintain government furnished real property and capital equipment. (Ref PWS C-5, Ch 2, para 5.2.3)	Provide safe and economic repair to government furnished real property and equipment.	0% Lot: number of times maintenance is required.	100 percent inspection annual checklist	3%
RS10 Perform Custodial housekeeping functions. (Ref 5.2.5 and Saylor Creek Range TE-2)	Range main buildings, towers, and main compound grounds must be cleaned and maintained as to ensure functionally and present a neat orderly appearance.	0% Lot: number of days in a month.	100 percent inspection weekly, quarterly, and semi-annual checklists.	3%

PERFORMANCE REQUIREMENTS SUMMARY
Saylor Creek/Juniper Butte Ranges, ID (B&G)

Solicitation No.
F-44650-99-R0002

REQUIRED SERVICE	STANDARD	PERFORMANCE REQUIREMENT	METHOD OF SURVEILLANCE	MAXIMUM PAY PERCENTAGE FOR MEETING THE PERFORMANCE REQUIREMENT
RS11 Provide Fire Protection and Crash Recovery as required. Develop and implement supporting training Ch 2, para 5.7 and Saylor Creek Range Annex para 4.3)	Ensure a responsive, effective fire suppression and crash recovery program exists to minimize damage to government property/resources.	0% Lot: number of operational days in a month	100 percent inspection semi-annual checklist	3%